REPAIR KIT RETURNS



Mechanics, when you send a Stewart-Warner heater with a bad burner to DS for repair, chances are they'll put in a new burner instead of repairing the old one.

That's because the burner repair kit, NSN 2540-00-255-0777, was left out of TM 9-2540-205-24&P.

Let DS know the repair kit is still available and that it works with Stewart-Warner models 10560C, 10560G, 10560M and 10560M24B1.

11



Item	PN/NSN	Qty
Nut, hex castellated	705587*	3
Wick	9390-01-070-5959**	1
Washer	5310-01-126-0466	2
Washer	705136	2
Washer, shouldered	5310-01-059-0988	1
Vaporizer, fuel	2910-01-124-9284**	1
Washer	5310-01-126-0467	1
Washer, flat	5310-01-137-6801	1
Shield, fuel vaporizer	2540-01-057-7443	1
Screw, machine	5305-01-136-8734	1
Screw	5305-01-066-3431	3

*Order on a DD Form 1348-6 using part number and CAGE 38385 from RIC AKZ.

**Listed as an unavailable or terminal item. Available only by ordering the burner repair kit.